National Transportation Safety Board NTSB ID: WAS01RA012 Most Critical Injury: Serious PRELIMINARY REPORT Occurrence Date: 07/10/2001 Investigated By: AVIATION ICAO Report Submitted: No Occurrence Type: Accident ETYBO Location/Time Nearest City/Place State Zip Code Local Time Time Zone **FDT** La Paz 00000 1630 Aircraft Information Aircraft Manufacturer Model/Series Number Registration Number 208B CP-2395 Cessna Type of Aircraft: Airplane Homebuilt Aircraft? No Fatal Minor Serious None 6 Injury Summary:

Air Medical Transport Flight: No

Narrative

Sightseeing Flight: No

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On July 10, 2001, at 1630 eastern daylight time, a Cessna 208B single-engine airplane, Bolivian registration CP-2395, was substantially damaged during a forced landing following a loss of engine power during intial takeoff climb from the La Paz International Airport, near La Paz Bolivia. The airline transport rated pilot, the co-pilot and 5 passengers were seriously injured, and 6 passengers sustained minor injuries. The airplane was being operated by Amaszonas Transportes Aereos S.A., of La Paz, Bolivia, on a scheduled domestic commuter flight. Visual meteorological conditions prevailed for the scheduled passenger flight for which a VFR flight plan was filed. The flight's intended destination was Rurrenabaque in the Province of Beni.

According to local authorities, the flight crew reported a loss of engine power to the control tower, approximately 6 minutes after takeoff from the airport.

The accident investigation is under the jurisdiction and control of the Government of Bolivia. Any further information may be obtained from:

Ministerio de Desarollo Economico Viceministerio de Transportes, Comunicaciones y Aeronautica Civil Direccion General de Aeronautica Civil (DGAC) Palacio de Comunicaciones. Cuarto Piso Avenida Mariscal Santa Cruz #1278 Casilla Postal 9360 La Paz, Bolivia

This report is for informational purposes only and contains information released by, or obtained for the Government of Bolivia.

TRANSO_
National Transportation Safety Board
O Z
PRELIMINARY REPORT
7 3 7
ÁYÍATIQN

NTSB ID: WAS01RA012

PRELIMINARY REPORT		Occurrence Date: 07/10/2001									
AYIATION ETYBOR	Occurrence Type: Accident										
Other Aircraft Involved							_				
Registration Number Airc	Aircraft Manufacturer				Model/Series Number				nber		
Accident Information							•				
Aircraft Damage: Substantial			Accid	dent C	occurred Dur	ing: Em	ergency de	scent/la	anding		
Property Damage: None											
Crew Name					Certificate No.			Injury			
Pilot On File				Or	On File			Serious			
2 On File				Or	On File			Serious			
3											
4											
5											
6											
Operator Information											
Name AMASZONAS TRANSPORTES A	ame Operator D MASZONAS TRANSPORTES AEREOS					esignator Code Doing Business					
Street Address City La Paz International Airport La F				ty Paz					State	Zip Code 00000	
-Type of Certificate(s) Held: None										•	
Air Carrier Operating Certificate(s):											
Operating Certificate:					Operator Certificate:						
Regulation Flight Conducted Under: Non-U.S., Commercial											
Type of Flight Operations Conducted:											
Flight Plan/Itinerary											
Type of Flight Plan Filed: VFR											
Last Departure Point					State Airport Idea		t Identifier	dentifier			
Same as Accident/Incident Location	n										
Destination					State	Airpor	Airport Identifier				
Rurrenabaque											
Weather Information							1				
Investigator's Source:				Faci	lity ID:	Observation Time (Local):					
Sky/Lowest Cloud Condition: Clear					Ft.						
Lowest Ceiling: None		F	Ft. AGL	V	isibility:	10	SM	Altim	neter:		"Hg
PF	RELIMINARY	INFORM	MATION -	- SUI	BJECT TO	CHAN	GE				Page 2

National Transportation Safety Board PRELIMINARY REPORT

NTSB ID: WAS01RA012

Occurrence Date: 07/10/2001

2 2									
AYIATION			Осс	urrence T	ype: Accident				
Weather Information		(Continued from page	e 2)						
Temperature:	°C	Dew Point:	°C	Wind D	Wind Direction:				
Wind Speed:	Kts	. Gusts:	Kts.	Weath	er Conditions at Accident	nditions			
Administration Data									
Notification From					Date	Local Time			
DGAC OF BOLIVIA						07/11/2001	0900		
FAA District Office/Coordinator				Investigator-In-Charge (IIC)					
SAN ANTONIO, TEXA ROBERT HERNANDE					HECTOR R. CASANOVA				
		<u> </u>							